OFFICE OF THE DISTRICT FIRE OFFICER
Karnataka Fire & Emergency Services
Haveri Fire Station
Haveri-581110.

email Id:- haveridfo@gmail.com Telephone:08375-232666/9480823663

No:64/ LRB/FSR/DFO/ HAVERI/2026. Dated:13-07-2026

To,

The Head Master,
Tagore Education Trust ®
Rotary Public School,
Ashok Circle, Station Road,Ranebennur Town
Ranebennur Taluk Haveri District-581115
Dise Code:29114100992.

Sub: Issue of **"Fire Safety Recommendation"** to ***"Tagore Education Trust ® Rotarry Public School, Ashok Circle, Station Road, Ranebennur Town Ranebennur Taluk Haveri District-581115.Dise Code:29114100992.***

Ref: 1.Your Application Dated:30-06-2026
2.No:18/LRB/FSR/FSO/RANEBENNUR/2026 Dated:07-07-2026
3.No:GBC(2)2100/2025 Dated:03-02-2026

With reference to the subject cited above, the Low Rise Educational Building of ***Tagore Education Trust ® Rotary Public School, Ashok Circle, Station Road, Ranebennur Town Ranebennur Taluk Haveri District-581115. Dise Code:29114100992***Was inspected by Fire station Officer, Ranebennur Fire station on **02-07-2026** with respect to Fire prevention, Fire fighting and Evacuation measures to be complied in the above premises and has submitted the details as under.

ANNEXURE-B

NBC-2016, PART-4, TABLE-7(II)3.1.3 group B Educational buildings Sub Division B-1 & B-2(these condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC-2016 are mandatory.)

Details Of The Building/Premises :-

1	Name and Address of the Applicant.	:	**The Head Master,** Tagore Education Trust ® Rotary Public School, Ashok Circle, Station Road,Ranebennur Town Ranebennur Taluk Haveri District-581115 Dise Code:29114100992.
2	Name and Address of the premises.	:	**The Head Master,** Tagore Education Trust ® Rotary Public School, Ashok Circle, Station Road, Ranebennur Town Ranebennur Taluk Haveri District-581115 Dise Code:29114100992.

13/07
DISTRICT FIRE OFFICER
HAVERI

Scanned with OKEN Scanner

3	Name and Address of the building owner.	:	The President/ Secretary, Dr.Basavaraj S Kelgar, Kelgar Medical Centre, Vinayaka Nagar,Ranebennur, RanebennurTaluk, Haveri District-581115
4.	Number of buildings	:	01 building
5.	Number of floors Block 01	:	Ground +02
6.	**Floor-wise details of occupancy:-**		
	Ground floor	:	Office Room-01, Principal Room-01 Class Room-06, Staff Room-01,Lab-01
	1st Floor	:	Class Room-11, Lab-01
	2nd Floor	:	Class Room-11, Lab-01
7.	Height of the building	:	10.40mtrs
8.	Site area	:	6000.00Sq.mtrs
9	Built-up area of each floor:-		
	Ground floor	:	558.08Sq.mtrs.
	1st Floor	:	558.08Sq.mtrs.
	2nd Floor		558.08Sq.mtrs
	Total built-up area	:	1674.24Sq.mtrs.
10.	Surrounding properties:-		
	East (S)	:	Residential House
	West (S)	:	Public Road
	North (F)	:	Public Road
	South(B)	:	Public Road
11.	**Set-back area available around the building :**		
	East (S)	:	00.50 mtrs
	West (S)	:	00.50 mtrs
	North (F)	:	01.00 mtrs
	South(B)	:	00.50 mtrs
Allowed setback (open space) should be maintained free from further obstruction/construction for easy movement of emergency vehicles.			

12/07

DISTRICT FIRE OFFICER
HAVERI

Scanned with OKEN Scanner

B. On inspection of this College premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view.

S.N (1)	Details (02)	Existing (03)			Recommendations (04)
1.	Accessibility to the premises	The Premises Is Accessible From 12.00 Mtrs Wide main Road Located On The Northern Side. It Is Hard Enough To Carry The Weight Of 45,000 kg's.			Adequate
2.	No. of entrances	provided 01gate Of Width 03.90mtr			The Allowed Entry Width Should be Extend to min 06.00mtrs
3.	Diesel Generators.	Not Provided			Diesel generator of Adequate capacity should be provided to supply alternative power supply.
4.	Staircase	Nos. Of Staircases	:	02 No's	**complied**
		Width Of Staircases	:	01.20mtr / 01.55mtr	
		Width Of Treads	:	30 cm / 30 cm	
		Height Of Risers	:	15 cm / 15 cm	
		Nos. Of Riser Per Flight	:	09 No's / 12 No's	
		Height Of Handrails	:	01 mtr / 01 mtr	
		Head Room Clearance	:	03 mtr / 03.10 mtr	
5.	Portable Fire extinguishers	Not Provided			1). 01 No CO_2 fire extinguisher of 4.5 kg capacity should be provided near each electrical panel board and electrical room. 2). 01 ABC extinguishers of 4 kg capacity should be provided in the kitchen. (If provide for the purpose of mid day meal). 3).One ABC type fire extinguishers of 6 kg capacity should be located as to be available within 100 Sqmtrs radius. 4). All the extinguishers suggested above should be with BIS marking and should be located at an easily accessible position without obstructing the normal passage and maintained periodically.
6.	Hose reel hose system	Not provided			**Not complied** Recommended to provide (one hose reel hose system for every 1000 sq.mtrs) the hose reel hose Is of minimum 19 mm dia and of 30 mtr length shall be provided to reach the farthest point of each floor and shut off

4/12/07
DISTRICT FIRE OFFICER
HAVERI

Scanned with OKEN Scanner

			branch having a nozzle of 05 mm size. The hose reel hose should be connected at each landing.
7.	Terrace water tank capacity	Provided 1000 ltr 02 Sintex	**Not complied** Recommended to provide an over head tank of 5000 ltrs capacity and this water tank should be kept exclusively fire fighting purpose only.
8.	Pump at the terrace tank level	Not Provided	**Not complied** Recommended to provide 01 No of electrical pump with output capacity of 450 lpm or of 05 HP capacity near terrace water storage tank with minimum pressure of 3.5 kg per cm^2 at remotest location.
9.	Escape routes	Not Marked	**Not complied** Direction in with the students / Inmates should have to move in the event of an emergency should be indicated in the corridor/passage as a guide during evacuation. These marking should be in Luminous Light /Paint.
10.	Fire order (Fire safety plans)	Not Displayed	Recommended to provide Fire safety indicating the details of actions to be taken in case of emergency shall be displayed near each staircase landings with the telephone numbers of **Ranebennur Fire Station 08373-269101**, and 101/112/22971550 /22971500/22971600 numbers& telephone numbers of nearest Ambulance Service in the building.
11.	No Smoking Board	Not Displayed	COPTA Sec-4 direction No-smoking area smoking here is an offence board written in kannada & English both language have been displayed at inside the entry and exit of ground floor.
12.	Fire Siren	Not Installed	A Fire siren shall be installed in the premises to inform the inmates/students in case of a fire emergency and evacuate the area
13.	Nominate One fire nodal officer	Not Nominated	A fire nodal office shall be nominated either from teaching or non-teaching staff.

4/13/07
DISTRICT FIRE OFFICER
HAVERI

Scanned with OKEN Scanner

14.	Fire fighting training	**Not Imparted**	**Not Complied.** At least 40% of employees shall be trained in basic fire fighting course at our R.A. Mundkur Fire and Emergency Services Training Academy, Bannerghatta Road, Bangalore-29.

Fire precautionary measures

a) Explosive and Flammable materials should not be stored in the store room, UPS room, Electrical panel area, Class room, Laboratory, and Electrical sum panel premises
b) Accumulation of combustible waste in and around the premises should be avoided.
c) The Exit ways shall be always kept clear without any obstruction
d) Liquefied petroleum gas (LPG) should not be stored in the building.
e) The doors shall not be kept locked/Latched during working hours and shall be free from obstruction
f) During the class hours the class room doors shall not be locked from inside to out side
g) As per Hon'ble Supreme court order all teachers and staffs shall be trained to handle safety equipments, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the fire safety day on April-14th of every Year by conducting fire safety drills with co-ordinate with fire service department.

Under the above circumstance The Karnataka Fire and Emergency Service Department is Issuing '**Fire Safety Recommendation'** to ***"Tagore Education Trust ® Rotary Public School, Ashok Circle, Station Road, Ranebennur Town Ranebennur Taluk Haveri District-581115.Dise Code:29114100992.***Subject to condition and compliance of the above recommendations in column-3 of serial-B within 03 months compliance to the under signed.

This **"Fire Safety Recommendation"** is valid for only One year from the date of issue and it is renewable.

All requirements recommended above are as per National Building code-2016 Part-4 clause 3.1.3 of Fire and Life safety will have to be complied with mandatorily.

Yours faithfully

13/07/2026

District Fire Officer
Karnataka Fire & Emergency Service
Haveri Dist

Principal
Rotary Public School
Ranebennur Dt: Haveri
Dise Code: 29114100992

Manager
Rotary Public School
Station Road, Ranebennur

SECRETARY
Tagore Education Society
Ranebennur

Scanned with OKEN Scanner